

ARMY ENGINEER DISTRICT ST LOUIS MO F/8 13/13  
NATIONAL DAM SAFETY PROGRAM, TRIPOLI VALLEY DAM (NO 30345), MIS--ETC(U)  
NOV 78 M J KLOSTERMAN, D W CARTER

NATIONAL DAM SAFETY PROGRAM, TRIPOLI VALLEY DAM (NO 30345), MIS--ETC(U)  
NOV 78 M J KLOSTERMAN, D W CARTER

NL

1000  
2000  
3000  
4000  
5000  
6000  
7000  
8000  
9000  
10000  
11000  
12000  
13000  
14000  
15000  
16000  
17000  
18000  
19000  
20000  
21000  
22000  
23000  
24000  
25000  
26000  
27000  
28000  
29000  
30000  
31000  
32000  
33000  
34000  
35000  
36000  
37000  
38000  
39000  
40000  
41000  
42000  
43000  
44000  
45000  
46000  
47000  
48000  
49000  
50000  
51000  
52000  
53000  
54000  
55000  
56000  
57000  
58000  
59000  
60000  
61000  
62000  
63000  
64000  
65000  
66000  
67000  
68000  
69000  
70000  
71000  
72000  
73000  
74000  
75000  
76000  
77000  
78000  
79000  
80000  
81000  
82000  
83000  
84000  
85000  
86000  
87000  
88000  
89000  
90000  
91000  
92000  
93000  
94000  
95000  
96000  
97000  
98000  
99000  
100000

END  
DATE  
FILMED  
11-81  
DTIC

LEVEL IV

DA106046

DTIC

OCT 21 1981

D

H

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A106 046	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Tripoli Valley Dam (MO 30345) Phelps County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Corps of Engineers, St. Louis District		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s)  N/A
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITOR National Dam Safety Program. Tripoli Valley Dam (MO 30345), Mississippi Kaskaskia St. Louis Basin, Phelps County, Missouri. Phase I Inspection		12. REPORT DATE November 1978
16. DISTRIBUTION STATEMENT Report.  Approved for release; distribution unlimited.		13. NUMBER OF PAGES Approximately 35
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
18. SUPPLEMENTARY NOTES		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

2

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

TRIPOLI VALLEY DAM  
PHELPS COUNTY, MISSOURI

MISSOURI INVENTORY NO. 30435

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

PREPARED BY: ST. LOUIS DISTRICT CORPS OF ENGINEERS  
FOR: GOVERNOR OF MISSOURI

DISTRIBUTION STATEMENT 1  
Approved for public release  
Distribution Unlimited

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam	Tripoli
State Located	Missouri
County Located	Phelps County
Stream	Tributary to Asher Hollow
Date of Inspection	6 September 1978

Tripoli Valley Dam was inspected by an interdisciplinary team of engineers from the St. Louis District, U. S. Army Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property. The inspection and assessment were made using the "Recommended Guidelines for Safety Inspection of Dams," developed by the Chief of Engineers, U. S. Army, Washington, D. C., with the help of several Federal and state agencies, professional engineering organizations, and private engineers.

Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. Failure would threaten the life and property of approximately 2 families downstream of the dam and cause appreciable damage to two homes, one farm building, one county road, one state road and one recreational area, all within a three-mile damage reach of the dam.

For its size and hazard category, this dam is required by the guidelines to pass from one-half the Probable Maximum Flood (PMF) to PMF. The PMF is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. This dam was evaluated using the one-half PMF because of the possible loss of human life downstream of the dam. It was found that the spillway is only capable of passing 10 percent of the PMF without overtopping the dam. Since the spillway is not capable of passing a minimum of one-half of the PMF without overtopping the dam and perhaps causing failure, the spillway is considered seriously inadequate and the dam is accordingly considered unsafe.

Other deficiencies visually observed by the inspection team were trees on embankment, obstruction of spillway, minor erosion of the upstream face of dam, and lack of erosion protection on the

upstream face of dam. Seepage and stability analyses comparable to the requirements of the guidelines are not on record; this is also a deficiency which should be rectified.

It is recommended that action be taken to implement the remedial measures listed herein in the near future. Any corrective works performed in relation to increasing the spillway size and/or dam height and stability and seepage investigations of the embankment should be made in accordance with analyses and design performed by an engineer experienced in the design of dams. These conclusions were reached by the undersigned inspection team members.

*for Michael J. Klosterman*  
MICHAEL J. KLOSTERMAN

Geologist  
St. Louis District  
Corps of Engineers

*David W. Carter*  
DAVID W. CARTER

Hydraulic Engineer  
St. Louis District  
Corps of Engineers

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Avail and/or	
Dist	Special
A	

*Andrew Heydinger*  
ANDREW HEYDINGER

Soils Engineer  
St. Louis District  
Corps of Engineers

*Chien H. Hsieh*  
CHIEN (NANCY) HSIEH

Hydraulic Engineer  
St. Louis District  
Corps of Engineers

SUBMITTED BY:

*Jack R. Uiem*  
Chief, Engineering Division

17 Nov 78

Date

APPROVED BY:

*Lem E. Muth*  
Colonel, CE, District Engineer

20 Nov 1978

Date

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
TRIPOLI VALLEY DAM - ID NO. 30435

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION 2 - ENGINEERING DATA		
2.1	Design	4
2.2	Construction	4
2.3	Operation	4
2.4	Evaluation	4
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	5
3.2	Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	8
4.2	Maintenance of Dam	8
4.3	Maintenance of Operating Facilities	8
4.4	Description of Any Warning System in Effect	8
4.5	Evaluation	8
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	9
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	10
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	11
7.2	Remedial Measures	11

APPENDIX

Hydrologic Computations



#### LIST OF PLATES

1. Vicinity Topography
2. Dam Profile and Cross Sections
3. Plan
4. Spillway Profile and Cross Sections

#### LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1	Downstream View
2	Looking Upstream From Spillway
3	Looking Along Crest of Dam
4	Upstream Face of Dam
5	Spillway
6	Looking Downstream From Spillway
7	Looking Towards Lake From Spillway
8	Spillway at Road Crossing
9	Discharge Valve
10	Marshy Area Near Downstream Toe of Dam



OVER VIEW OF DAM

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
TRIPOLI VALLEY DAM ID NO. 30435

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of the Tripoli Valley Dam be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances.

(1) The dam is an earth structure built in a narrow valley. The topography adjacent to the valley is rolling to steep. The earth embankment is composed of gravelly clay. Topography in the vicinity of the dam is shown on PLATE 1.

(2) Appurtenant structures consist of an ungated spillway and a valve controlled, 6-inch diameter, discharge pipe through the dam.

(3) Pertinent physical data are given in paragraph 1.3 below.

b. Location. The dam is located in the eastern portion of Phelps County, Missouri, in the SE 1/4 of the SE 1/4 of T37N, R6W of the Maramec Spring, Missouri Quadrangle Sheet.

c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, this dam and impoundment is in the small size category.

d. Hazard Classification. Criteria for determining hazard classification are presented in the same report as referenced in paragraph 1.2c above. Based on referenced criteria, this dam is in the High Hazard Classification.

e. Ownership. This dam is owned by Clara Sooter, 3945 Bayless, St. Louis, Missouri 63125.

f. Purpose of Dam. The dam forms a 6-acre recreational lake.

g. Design and Construction History. The Tripoli Valley Dam was built in 1965 by the Smith Brothers Construction Company. No plans were drawn up for construction of the dam.

h. Normal Operating Procedure. Operating procedures at the dam consist of releases through the discharge pipe whenever the pool appears to be too high to the owner.

### 1.3 PERTINENT DATA

a. Combined Drainage and Lake Area - 269 acres.

b. Discharge at Damsite.

(1) Estimated ungated spillway capacity at maximum pool elevation - 270 cfs.

(2) Estimated experienced maximum flood at damsite - Unknown.

c. Elevation (Based on an assumed datum of 800 feet msl).

(1) Top of dam (minimum elevation of earth embankment) - 898.0.

(2) Spillway crest - 895.1.

(3) There is no low head outlet.

(4) Maximum tailwater - Unknown.

(5) Streambed at centerline of dam - estimated 873 feet.

d. Reservoir Length of Maximum Pool - 1000 feet.

e. Storage (Acre-feet) at Top of Dam Estimated. 68.

f. Reservoir Surface (Acres).

- (1) Top of dam - 8.
- (2) Spillway crest - 6.

g. Dam.

- (1) Type - earth.
- (2) Length - 435 feet.
- (3) Height - 26 feet.
- (4) Top width - 29 feet.
- (5) Side Slopes -
  - (a) Downstream - 1.5H on 1V (varies)
  - (b) Upstream - 1H on 1V (varies)
- (6) Zoning - unknown.
- (7) Impervious Core - unknown.
- (8) Cutoff - unknown.
- (9) Grout curtain - unknown.

h. Diversion and Regulating Tunnel. None.

i. Spillway.

- (1) Type - Ungated
- (2) Length of weir - 65 feet.
- (j) Regulating Outlets - 6-inch diameter discharge pipe

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

No design data were available on this dam.

### 2.2 CONSTRUCTION

The dam was built in 1965 by the Smith Brother Construction Co. No additional construction data are available.

### 2.3 OPERATION

The maximum reservoir loading on the dam is not known. All releases are through an uncontrolled spillway and a discharge pipe.

### 2.4 EVALUATION

- a. Availability. No design data was available.
- b. Adequacy. Seepage and stability analyses comparable to the requirements of the "Recommend Guidelines for Safety Inspection of Dam" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for the appropriate loading conditions and made a matter of record.
- c. Validity. No valid engineering design data or construction data were available.

### SECTION 3 - VISUAL INSPECTION

#### 3.1 FINDINGS

a. General. The owner did not accompany the inspection team. There is no other lake in the watershed that would affect Tripoli Lake.

b. Project Geology.

(1) Tripoli Valley is a tributary to a losing (or dry) stream in Asher Hollow which is itself a tributary to the Meramec River. The area is approximately 2-1/2 miles south of Meramec Springs and has the land form features and subsurface hydrologic characteristics typical of karst terrain.

(2) The Tripoli Valley dam and watershed are underlain by Gasconade Dolomite. The damsite itself is founded on residuum and bedrock of the upper Gasconade and, although the divides forming the limits of the watershed may have some Roubidoux residuum, they are composed primarily of Gasconade residuum. The bedrock in the spillway described as "tan to light brown, moderately hard, sedimentary carbonate rock" (paragraph 3.1.b(1)) is an outcrop of Gasconade Dolomite.

(3) Inspection of the watershed area indicated several areas of seeps and springs but, since it had recently rained, it was not possible to determine if they were perennial or intermittent. The small stream leading into the reservoir appears to flow continuously and there is no reason to question that some of the springs are perennial (paragraph 3.1.b(2)).

(4) The "large area with standing water" (paragraph 3.1.c(5)) located on the downstream face near the toe on the east side of the dam appears to be occurring as seepage through the right abutment. The bedrock has been extensively weathered, there is a very irregular and uneven bedrock surface, and it seems very likely that this seepage is occurring through residuum and weathered dolomite underlying the abutment.

(5) Adverse conditions prevented a close inspection of the left abutment. However, no outcrops of particular geologic significance were noted from a safe distance and, since no seepage was reported in the preliminary report, a close inspection was not considered critical.

c. Dam.

(1) No detrimental settlement, cracking, or sinkholes were observed in or near the earth embankments. An embankment cross section at the maximum height section for the dam is shown on PLATE 2. No animal burrows were noted at the dam.

(2) There are some small trees on the dam, mostly on the downstream slope, which include willow trees near the toe where the moist conditions were noted, oak trees up the slope from the willows, and fruit trees. The root systems of the trees constitute a potential seepage hazard. In addition to the trees, there is some heavy vegetation which increases the likelihood of animal burrows which could also create potential seepage hazards.

(3) Based on surface observations, the dam is composed of gravelly clay.

(4) There is no riprap on the dam embankment.

(5) A large area with standing water was observed on the downstream face near the toe on the east side of the dam. The standing water, willow trees and heavy vegetation indicates that there is either a spring in the abutment or there is a steady seepage condition.

(6) There is some erosion on the upstream face of the dam which is caused by surface washing of soil loosened by livestock on the dam.

c. Appurtenant Structures.

(1) Appurtenant structures at Tripoli Dam consist of a spillway and a 6-inch diameter iron pipe with a downstream valve.

(2) The spillway at Tripoli Lake is approximately 65 feet wide and is earth with some grass cover. Downstream of the dam rock outcrops occur in the spillway. The spillway eventually flows into a channel that flows along a "stair step" rock outcrop. A few trees at the entrance of the spillway were observed.

d. Reservoir Area. No pertinent problems were noted in the reservoir area.

e. Downstream Channel. The downstream channel flows down a rock outcrop, across a gravel road and into a pasture. It has some trees, logs and debris in it.



### 3.2 EVALUATION

Trees and thick vegetation on the embankment and insufficient erosion protection on the upstream face of the dam and spillway are deficiencies which should be corrected. Soft, spongy ground conditions could lead to instability of the embankment if uncorrected. The need for possible seepage control measures should be based upon analysis of the stability and seepage conditions by a professional engineer experienced in the design and construction of dams.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

Operational procedures consist of opening the valve downstream of the embankment to allow water to flow from the reservoir. This lowers the reservoir and reduces the time of flow over the spillway and the fish losses associated with flow over the spillway.

### 4.2 MAINTENANCE OF DAM

Little maintenance is apparent as evidenced by the vegetative cover and the small trees on the embankment and spillway. There reportedly was a large leak in the west side of the dam which was corrected.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

None mentioned.

### 4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

No warning system is known to exist.

### 4.5 EVALUATION

Additional maintenance in the form of clearing and mowing the embankment is recommended.

## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

a. Design Data. No design data were available for Tripoli Valley Dam.

b. Experience Data. The drainage area and lake surface area were developed from USGS Maramec Spring, Missouri, Quadrangle Map. The spillway and outlet data were surveyed during the inspection.

c. Visual Observations.

(1) A valve controlled, 6-inch diameter, steel pipe through the dam has been used to regulate releases. The pipe can be used for drawdown of the lake. (See photograph 9).

(2) A earth spillway with some grass cover located at the right side of the dam consists of a channel with a parallel guide levee at left and continuing downstream through a narrow rocky channel to a road right downstream of the dam. (See PLATES 5 and 4 and photographs 5 through 8). The grass on the spillway and channel is not in good condition and rocks show through some of the bare areas at channel.

(3) A few trees at the entrance of the spillway were observed.

d. Overtopping Potential. Tripoli Valley Dam can be overtopped by any flood greater than 10 percent of the Probable Maximum Flood (PMF). The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. Tripoli Valley Dam can be overtopped by a 1 percent chance flood. A 1 percent chance flood is a flood with a 1 percent chance of being exceeded in any given year. The guidelines require that a dam of this hazard potential (high) and size pass at least 50 percent of the PMF without overtopping the dam. The maximum discharge over the dam for 50 percent of the PMF is 2200 cfs. The maximum depth of flow over the low point of the earth embankment by 50 percent of the PMF is 2.0 feet. The duration of overtopping is 5.3 hours.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations of the dam and spillway are discussed and evaluated in Sections 3 and 5. The dam has no other appurtenant structures.

b. Design and Construction Data. None available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions and made matter of record.

c. Operating Records. No operating records were available.

d. Post Construction Changes. According to the owner's father, a large leak on the right side of the dam was repaired.

e. Seismic Stability. Tripoli Lake is located in Seismic Zone 1, for which the recommended guidelines for inspection assign a "moderate" damage probability. The relatively low height and the type of material of which the dam was constructed minimize the likelihood of failure due to earthquake shock.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

a. Safety. Several items are deficient which should be corrected. No erosion protection exists on the upstream slope of the dam. Cattle on the upstream slope and on the embankment loosens the earth and causes surface erosion. The upstream face of the embankment is not sufficiently protected against erosion. The left side of the spillway, which effectively is a protection dike for the area downstream of the embankment, is not sufficiently protected against erosion. Trees and heavy vegetation on the embankment provide a potential seepage hazard and animal habitat. The spillway is not adequately protected against erosion. The capacity of the spillway is insufficient to pass one-half of the PMF to PMF without overtopping the dam.

b. Adequacy of Information. The statements and recommendations in this report are based on visual observations and verbal discussions. Seepage and stability analyses are not on record as prescribed in the recommended guidelines. This is considered a deficiency which should be corrected.

c. Urgency. We recommend the remedial measures listed in Section 7.2 be accomplished in the near future. The item recommended in Paragraph 7.2d should be pursued on a high-priority basis.

d. Necessity for Phase II. No Phase II inspection is recommended.

### 7.2 REMEDIAL MEASURES

The following remedial measures are recommended:

- a. Remove trees and cut heavy vegetation on the embankment.
- b. Fill any animal burrows found during clearing.
- c. Establish and maintain a grass cover on the embankment.
- d. The spillway size and/or height of the dam should be increased to pass a minimum of one-half of the Probable Maximum Flood without overtopping the dam.
- f. A stability and seepage analysis of the dam should be performed by a professional engineer experienced in the design and

construction of dams. These analyses should provide a design of seepage control works and other remedial measures related to embankment stability and erosion protection.

g. A detailed inspection of the dam and spillway should be made every two to five years by a professional engineer experienced in the design and construction of dams.

**APPENDIX**  
**HYDROLOGIC COMPUTATIONS**

## HYDROLOGIC AND HYDRAULIC ANALYSIS METHODOLOGY

1. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for a reservoir routing. The Probable Maximum Precipitation for those dams in the high hazard potential category is derived and determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33." Reduction factors have not been applied. A 24-hour storm duration is assumed with the 24-hour rainfall depths distributed over 6-hour periods in accordance with procedures outlined in EM 1110-2-1411 (SPF Determination). The maximum 6-hour rainfall period is then distributed to hourly increments by the same criteria. Within-the-hour distribution is based upon NOAA Technical Memorandum NWS HYDRO-35. The non-peak 6-hour rainfall periods are distributed uniformly. All distributed values are arranged in a critical sequence by the SPF criteria. The final inflow hydrograph is produced by deduction of infiltration losses appropriate to the soil, land use, and antecedent moisture conditions.

2. The reservoir routing is accomplished by using Modified Puls routing techniques wherein the flood hydrograph is routed through lake storage. Hydraulic capacities of the outlet works, spillway, and crest of dam are used as outlet controls in the routing. Storage in the pool area is defined by an elevation-storage capacity curve. The hydraulic capacity of the outlet works, spillway, and top of dam are defined by elevation-discharge curves.

3. Dam overtopping analysis has been conducted by hydrologic methods for this dam and lake. This computation determines the percentage of the PMF hydrograph that the reservoir can contain without the dam being overtopped. An output summary in the hydrologic appendix displays this information as well as other characteristics of the simulated dam overtopping.

4. The above analysis has been accomplished for this report using the systemized computer program HEC-1 (Dam Safety Version), July 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. The numeric parameters estimated for this site are listed on the attached computer printout. Definitions of these variables are contained in the "User's Manual" for the computer program.

5. The rating curve for Tripoli Valley Lake Dam was computed by using HEC-2 backwater program to get a rating curve for the spillway. Flow over the dam was computed by using the broad-crested weir equation for sections of the dam of equal crest elevation. A "C" value of 3.0 was used for the weir equation.



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (REC-1)  
 JAP SAFETY VERSION JULY 1978  
 LAST MODIFICATION 29 AUG 78  
 \*\*\*\*\*

1	A	DAH	INSPECTION	VALLEY	MAXIMUM	DAY	FLOOD	0	0	0	-3	0
2	A	TRIPOLI										
3	A	PROARLE										
4	B	288	0	5	0	0	0	0	0	0	0	0
5	B1	5										
6	J	1	9	1								
7	J1	.01	.05	.10	.15	.20	.25	.30	.50	1.0		
8	K	0		0	0	0	0	1				
9	K1	SUBARLA		RUNOFF		FOR	TRIPOLI	DAH				
10	H	1	2	.420	0	0	1.0					
11	P	0	20	100	120	130						
12	L	0	0	0	0	0	0	-1	-89	0	.03	
13	M2	0	.19	0	0							
14	X	-10	-1	3.0								
15	K	1	2	0	0	0	0	1				
16	K1	RESERVOIR		ROUTING		FOR	TRIPOLI	DAH				
17	Y	0	0	0	1	1						
18	Y1	1	0	0	0	0	0	-895.1	-1			
19	Y4	895	896	897	898	899	900	901	902	903	904	
20	Y5	0	50	120	270	920	2214	4166	6535	9251	12268	
21	SA	0	6	8	8.3							
22	SE	8/1	895.1	898	905							
23	SS	895.1										
24	SO	898.0										
25	K	99										

PREVIEW OF SEQUENCE OF SPREAD NETWORK CALCULATIONS

KURUFF HYDROGRAPH AT  
 ROUTE HYDROGRAPH TO  
 END OF NETWORK

1 2

THIS PAGE IS POST SECURITY PRACTICE DUE  
 1915 PAGE IS POST SECURITY PRACTICE DUE

100-100000

**FOR INFORMATION:**

[illegible]

MULTI-PLANE ANALYSIS TO BE PERFORMED

1 - OCT 1946 - 1 - 114V1246

Rate	10	20	30	40	50	60	70	80	90	100
1.00	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.10	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.20	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.30	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.40	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.50	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.60	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.70	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.80	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
1.90	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10
2.00	.01	.02	.03	.04	.05	.06	.07	.08	.09	.10

2000

SUE-APLA EMPLOY COMPANY

SUBAREA	RUTOFF			FOR			TRIPOLL		
	TSIAO	ICOPP	ICEOF	ISAFE	JPLT	JPTT	INADP	ISTAGE	IAUTO
1	0	0	0	0	0	0	1	0	0

## HYDROGRAPHIC DATA

AMOUNT	LOAN	TAKE	SWAP	TRFSD	TRFPG	PATIO	ISPOV	ISAME	LOCAL
1	1	.42	0.00	.42	1.00	0.000	0	0	0

22. 11. 1941

DATE	PLD	RO	R12	R24	R48	R96
0000	26.00	100.00	120.00	130.00	0.00	0.00
0001	00.00					

**LÜŠA PATA**

LEOPT	STAGE	DATE	FTOL	LRAP	STES	FTOP	STETL	CUSTL	ALSPX	FTTIP
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-09.00	0.00	.03

CURVE NO - 19.00 VFTRESS - -1.00 EFFECT CN - 10.00

UNIT: IX: PROCAP: DATA

[illegible]

RECEIVED DA 17A

```
STATS=07.00  ORCSP= -.10  RTIME= 3.00
```

UNIT HYDROGRAPH 13 END OF PERIOD ORDINATES, TC= 0.00 HOURS, LAG= .19 VOL= 1.00							
	735.	866.	647.	194.	108.	60.	33.
228.							
10.	1	6.	3.				

THIS PAGE IS UNCLASSIFIED  
DATE 01-01-2001 BY 60322 UCBAW

HO-DA	HR-RE	PERIOD	RAIN	EXCS	LOSS	ED-OF-PERIOD FLOW	PO-DA	DR-FT	PERIOD	RATE	PYCS	LOSS	COPP Q
1.01	.05	1	.01	.00	.01	4.	1.01	12.05	145	.22	.21	.01	260.
1.01	.10	2	.01	.00	.01	4.	1.01	12.10	146	.22	.21	.01	363.
1.01	.15	3	.01	.00	.01	4.	1.01	12.15	147	.22	.21	.01	486.
1.01	.20	4	.01	.00	.01	4.	1.01	12.20	148	.22	.21	.01	577.
1.01	.25	5	.01	.00	.01	4.	1.01	12.25	149	.22	.21	.00	626.
1.01	.30	6	.01	.00	.01	3.	1.01	12.30	150	.22	.21	.00	654.
1.01	.35	7	.01	.00	.01	3.	1.01	12.35	151	.22	.21	.00	679.
1.01	.40	8	.01	.00	.01	3.	1.01	12.40	152	.22	.21	.00	679.
1.01	.45	9	.01	.00	.01	3.	1.01	12.45	153	.22	.21	.00	685.
1.01	.50	10	.01	.00	.01	3.	1.01	12.50	154	.22	.21	.00	688.
1.01	.55	11	.01	.00	.01	3.	1.01	12.55	155	.22	.21	.00	690.
1.01	1.00	12	.01	.00	.01	3.	1.01	13.00	156	.22	.21	.00	691.
1.01	1.05	13	.01	.00	.01	2.	1.01	13.05	157	.26	.26	.00	702.
1.01	1.10	14	.01	.00	.01	2.	1.01	13.10	158	.26	.26	.00	734.
1.01	1.15	15	.01	.00	.01	2.	1.01	13.15	159	.26	.26	.00	714.
1.01	1.20	16	.01	.00	.01	2.	1.01	13.20	160	.26	.26	.00	800.
1.01	1.25	17	.01	.00	.01	2.	1.01	13.25	161	.26	.26	.00	815.
1.01	1.30	18	.01	.00	.01	2.	1.01	13.30	162	.26	.26	.00	824.
1.01	1.35	19	.01	.00	.01	2.	1.01	13.35	163	.26	.26	.00	829.
1.01	1.40	20	.01	.00	.01	2.	1.01	13.40	164	.26	.26	.00	832.
1.01	1.45	21	.01	.00	.01	3.	1.01	13.45	165	.26	.26	.00	834.
1.01	1.50	22	.01	.00	.01	4.	1.01	13.50	166	.26	.26	.00	835.
1.01	1.55	23	.01	.00	.01	5.	1.01	13.55	167	.26	.26	.00	836.
1.01	2.00	24	.01	.00	.01	6.	1.01	14.00	168	.26	.26	.00	837.3
1.01	2.05	25	.01	.00	.01	6.	1.01	14.05	169	.33	.32	.00	852.
1.01	2.10	26	.01	.00	.01	7.	1.01	14.10	170	.33	.32	.00	859.
1.01	2.15	27	.01	.00	.01	8.	1.01	14.15	171	.33	.32	.00	856.
1.01	2.20	28	.01	.00	.01	9.	1.01	14.20	172	.33	.32	.00	998.
1.01	2.25	29	.01	.00	.01	10.	1.01	14.25	173	.33	.32	.00	1020.
1.01	2.30	30	.01	.00	.01	10.	1.01	14.30	174	.33	.32	.00	1033.
1.01	2.35	31	.01	.00	.01	11.	1.01	14.35	175	.33	.32	.00	1040.
1.01	2.40	32	.01	.00	.01	12.	1.01	14.40	176	.33	.32	.00	1044.
1.01	2.45	33	.01	.00	.01	13.	1.01	14.45	177	.33	.32	.00	1047.
1.01	2.50	34	.01	.00	.01	13.	1.01	14.50	178	.33	.32	.00	1048.
1.01	2.55	35	.01	.00	.01	14.	1.01	14.55	179	.33	.32	.00	1049.
1.01	3.00	36	.01	.00	.01	15.	1.01	15.00	180	.33	.32	.00	1050.
1.01	3.05	37	.01	.01	.01	15.	1.01	15.05	181	.20	.20	.00	1022.
1.01	3.10	38	.01	.01	.01	16.	1.01	15.10	182	.40	.39	.00	974.
1.01	3.15	39	.01	.01	.01	16.	1.01	15.15	183	.40	.35	.00	1008.
1.01	3.20	40	.01	.01	.01	17.	1.01	15.20	184	.59	.59	.00	1142.
1.01	3.25	41	.01	.01	.01	17.	1.01	15.25	185	.69	.69	.00	1393.
1.01	3.30	42	.01	.01	.01	18.	1.01	15.30	186	1.68	1.67	.01	1504.
1.01	3.35	43	.01	.01	.01	19.	1.01	15.35	187	2.77	2.76	.01	3112.
1.01	3.40	44	.01	.01	.01	19.	1.01	15.40	188	1.09	1.09	.00	4524.
1.01	3.45	45	.01	.01	.01	20.	1.01	15.45	189	.69	.69	.00	4861.
1.01	3.50	46	.01	.01	.01	20.	1.01	15.50	190	.59	.59	.00	4181.
1.01	3.55	47	.01	.01	.01	21.	1.01	15.55	191	.40	.39	.00	3225.
1.01	4.00	48	.01	.01	.01	21.	1.01	16.00	192	.40	.39	.00	2499.
1.01	4.05	49	.01	.01	.01	21.	1.01	16.05	193	.30	.30	.00	1567.
1.01	4.10	50	.01	.01	.01	22.	1.01	16.10	194	.30	.30	.00	1584.
1.01	4.15	51	.01	.01	.01	22.	1.01	16.15	195	.30	.30	.00	1332.
1.01	4.20	52	.01	.01	.01	23.	1.01	16.20	196	.30	.30	.00	1176.
1.01	4.25	53	.01	.01	.01	23.	1.01	16.25	197	.30	.30	.00	1601.
1.01	4.30	54	.01	.01	.01	24.	1.01	16.30	198	.30	.30	.00	1044.

THIS COPY IS FROM THE  
FROM COPY 1

THIS PAGE  
IS BLANK

1.01	4.35	55	.01	.01	.01	24.	1.01	16.35	194	.30	.30	.00	1014.
1.01	4.40	56	.01	.01	.01	24.	1.01	16.40	200	.30	.30	.00	997.
1.01	4.45	57	.01	.01	.01	25.	1.01	16.45	201	.30	.30	.00	990.
1.01	4.50	58	.01	.01	.01	25.	1.01	16.50	202	.30	.30	.00	987.
1.01	4.55	59	.01	.01	.01	25.	1.01	16.55	203	.30	.30	.00	985.
1.01	5.00	60	.01	.01	.01	26.	1.01	17.00	204	.30	.30	.00	985.
1.01	5.05	61	.01	.01	.01	26.	1.01	17.05	205	.24	.24	.00	970.
1.01	5.10	62	.01	.01	.01	26.	1.01	17.10	206	.24	.24	.00	972.
1.01	5.15	63	.01	.01	.01	27.	1.01	17.15	207	.24	.24	.00	966.
1.01	5.20	64	.01	.01	.01	27.	1.01	17.20	208	.24	.24	.00	964.
1.01	5.25	65	.01	.01	.01	27.	1.01	17.25	209	.24	.24	.00	962.
1.01	5.30	66	.01	.01	.01	28.	1.01	17.30	210	.24	.24	.00	965.
1.01	5.35	67	.01	.01	.01	28.	1.01	17.35	211	.24	.24	.00	962.
1.01	5.40	68	.01	.01	.01	28.	1.01	17.40	212	.24	.24	.00	978.
1.01	5.45	69	.01	.01	.01	28.	1.01	17.45	213	.24	.24	.00	976.
1.01	5.50	70	.01	.01	.01	29.	1.01	17.50	214	.24	.24	.00	975.
1.01	5.55	71	.01	.01	.01	29.	1.01	17.55	215	.24	.24	.00	974.
1.01	6.00	72	.01	.01	.01	29.	1.01	18.00	216	.24	.24	.00	974.
1.01	6.05	73	.07	.05	.03	31.	1.01	18.05	217	.02	.02	.00	974.
1.01	6.10	74	.07	.05	.02	67.	1.01	18.10	218	.02	.02	.00	965.
1.01	6.15	75	.07	.05	.02	101.	1.01	18.15	219	.02	.02	.00	457.
1.01	6.20	76	.07	.05	.02	125.	1.01	18.20	220	.02	.02	.00	409.
1.01	6.25	77	.07	.05	.02	145.	1.01	18.25	221	.02	.02	.00	367.
1.01	6.30	78	.07	.05	.02	156.	1.01	18.30	222	.02	.02	.00	329.
1.01	6.35	79	.07	.06	.02	164.	1.01	18.35	223	.02	.02	.00	294.
1.01	6.40	80	.07	.06	.02	170.	1.01	18.40	224	.02	.02	.00	264.
1.01	6.45	81	.07	.06	.02	175.	1.01	18.45	225	.02	.02	.00	236.
1.01	6.50	82	.07	.06	.01	179.	1.01	18.50	226	.02	.02	.00	212.
1.01	6.55	83	.07	.06	.01	183.	1.01	18.55	227	.02	.02	.00	190.
1.01	7.00	84	.07	.06	.01	186.	1.01	19.00	228	.02	.02	.00	170.
1.01	7.05	85	.07	.06	.01	188.	1.01	19.05	229	.02	.02	.00	152.
1.01	7.10	86	.07	.06	.01	191.	1.01	19.10	230	.02	.02	.00	136.
1.01	7.15	87	.07	.06	.01	193.	1.01	19.15	231	.02	.02	.00	122.
1.01	7.20	88	.07	.06	.01	195.	1.01	19.20	232	.02	.02	.00	110.
1.01	7.25	89	.07	.06	.01	197.	1.01	19.25	233	.02	.02	.00	98.
1.01	7.30	90	.07	.06	.01	198.	1.01	19.30	234	.02	.02	.00	85.
1.01	7.35	91	.07	.06	.01	200.	1.01	19.35	235	.02	.02	.00	79.
1.01	7.40	92	.07	.06	.01	202.	1.01	19.40	236	.02	.02	.00	71.
1.01	7.45	93	.07	.06	.01	203.	1.01	19.45	237	.02	.02	.00	70.
1.01	7.50	94	.07	.06	.01	204.	1.01	19.50	238	.02	.02	.00	70.
1.01	7.55	95	.07	.06	.01	206.	1.01	19.55	239	.02	.02	.00	70.
1.01	8.00	96	.07	.06	.01	207.	1.01	20.00	240	.02	.02	.00	70.
1.01	8.05	97	.07	.06	.01	207.	1.01	20.05	241	.02	.02	.00	70.
1.01	8.10	98	.07	.07	.01	209.	1.01	20.10	242	.02	.02	.00	70.
1.01	8.15	99	.07	.07	.01	210.	1.01	20.15	243	.02	.02	.00	70.
1.01	8.20	100	.07	.07	.01	211.	1.01	20.20	244	.02	.02	.00	70.
1.01	8.25	101	.07	.07	.01	212.	1.01	20.25	245	.02	.02	.00	70.
1.01	8.30	102	.07	.07	.01	213.	1.01	20.30	246	.02	.02	.00	70.
1.01	8.35	103	.07	.07	.01	213.	1.01	20.35	247	.02	.02	.00	70.
1.01	8.40	104	.07	.07	.01	214.	1.01	20.40	248	.02	.02	.00	70.
1.01	8.45	105	.07	.07	.01	215.	1.01	20.45	249	.02	.02	.00	70.
1.01	8.50	106	.07	.07	.01	216.	1.01	20.50	250	.02	.02	.00	70.
1.01	8.55	107	.07	.07	.01	216.	1.01	20.55	251	.02	.02	.00	70.
1.01	9.00	108	.07	.07	.01	217.	1.01	21.00	252	.02	.02	.00	70.
1.01	9.05	109	.07	.07	.01	217.	1.01	21.05	253	.02	.02	.00	70.
1.01	9.10	110	.07	.07	.01	217.	1.01	21.10	254	.02	.02	.00	70.
1.01	9.15	111	.07	.07	.01	217.	1.01	21.15	255	.02	.02	.00	70.

1.01	9.20	112	.07	.07	.00	219.	1.01	21.20	256	.02	.02	.00	.00	70.
1.01	9.25	113	.07	.07	.00	219.	1.01	21.25	257	.02	.02	.00	.00	70.
1.01	9.30	114	.07	.07	.00	220.	1.01	21.30	258	.02	.02	.00	.00	70.
1.01	9.35	115	.07	.07	.00	220.	1.01	21.35	259	.02	.02	.00	.00	70.
1.01	9.40	116	.07	.07	.00	221.	1.01	21.40	260	.02	.02	.00	.00	70.
1.01	9.45	117	.07	.07	.00	221.	1.01	21.45	261	.02	.02	.00	.00	70.
1.01	9.50	118	.07	.07	.00	222.	1.01	21.50	262	.02	.02	.00	.00	70.
1.01	9.55	119	.07	.07	.00	222.	1.01	21.55	263	.02	.02	.00	.00	70.
1.01	10.00	120	.07	.07	.00	222.	1.01	22.00	264	.02	.02	.00	.00	70.
1.01	10.05	121	.07	.07	.00	223.	1.01	22.05	265	.02	.02	.00	.00	70.
1.01	10.10	122	.07	.07	.00	223.	1.01	22.10	266	.02	.02	.00	.00	70.
1.01	10.15	123	.07	.07	.00	223.	1.01	22.15	267	.02	.02	.00	.00	70.
1.01	10.20	124	.07	.07	.00	224.	1.01	22.20	268	.02	.02	.00	.00	70.
1.01	10.25	125	.07	.07	.00	224.	1.01	22.25	269	.02	.02	.00	.00	70.
1.01	10.30	126	.07	.07	.00	224.	1.01	22.30	270	.02	.02	.00	.00	70.
1.01	10.35	127	.07	.07	.00	224.	1.01	22.35	271	.02	.02	.00	.00	70.
1.01	10.40	128	.07	.07	.00	225.	1.01	22.40	272	.02	.02	.00	.00	70.
1.01	10.45	129	.07	.07	.00	225.	1.01	22.45	273	.02	.02	.00	.00	70.
1.01	10.50	130	.07	.07	.00	225.	1.01	22.50	274	.02	.02	.00	.00	70.
1.01	10.55	131	.07	.07	.00	225.	1.01	22.55	275	.02	.02	.00	.00	70.
1.01	11.00	132	.07	.07	.00	226.	1.01	23.00	276	.02	.02	.00	.00	70.
1.01	11.05	133	.07	.07	.00	226.	1.01	23.05	277	.02	.02	.00	.00	70.
1.01	11.10	134	.07	.07	.00	226.	1.01	23.10	278	.02	.02	.00	.00	70.
1.01	11.15	135	.07	.07	.00	226.	1.01	23.15	279	.02	.02	.00	.00	70.
1.01	11.20	136	.07	.07	.00	226.	1.01	23.20	280	.02	.02	.00	.00	70.
1.01	11.25	137	.07	.07	.00	227.	1.01	23.25	281	.02	.02	.00	.00	70.
1.01	11.30	138	.07	.07	.00	227.	1.01	23.30	282	.02	.02	.00	.00	70.
1.01	11.35	139	.07	.07	.00	227.	1.01	23.35	283	.02	.02	.00	.00	70.
1.01	11.40	140	.07	.07	.00	227.	1.01	23.40	284	.02	.02	.00	.00	70.
1.01	11.45	141	.07	.07	.00	227.	1.01	23.45	285	.02	.02	.00	.00	70.
1.01	11.50	142	.07	.07	.00	227.	1.01	23.50	286	.02	.02	.00	.00	70.
1.01	11.55	143	.07	.07	.00	228.	1.01	23.55	287	.02	.02	.00	.00	70.
1.01	12.00	144	.07	.07	.00	228.	1.02	0.00	288	.02	.02	.00	.00	70.
SUM										33.80	32.40	1.40	10.018.	
										( 859. )	( 823. )	( 35. )	( 3050.41 )	

PROPERTY REACTION

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				.01	.05	.10	.15	.20	.25	.30	.50	1.00
RATIOS APPLIED TO FLOWS												
HYDROGRAPH AT	1	.42	1	49.	243.	486.	729.	972.	1215.	1458.	2430.	4861.
	(	1.09)	(	1.38)	6.88)	13.76)	20.65)	27.53)	34.41)	41.29)	68.82)	137.64)
ROUTED TO	2	.42	1	18.	93.	235.	522.	764.	1037.	1303.	2229.	4642.
	(	1.09)	(	.50)	2.64)	6.67)	14.70)	21.64)	29.37)	36.89)	63.11)	131.44)

# SUMMARY OF DAM SAFETY ANALYSIS


TRIPOLI VALLEY DAM


INITIAL VALVE	SPILLWAY CREST	TOP OF DAM
895.10	895.10	898.60
48.	48.	68.
3.	3.	270.

RATIO OF PPE	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.01	0.00	50.	18.	0.00	16.17	0.00
.05	0.00	58.	93.	0.00	16.08	0.00
.10	0.00	67.	235.	0.00	16.00	0.00
.15	.39	72.	522.	.58	15.92	0.00
.20	.76	75.	764.	.83	15.83	0.00
.25	1.09	77.	1037.	1.25	15.83	0.00
.30	1.30	79.	1303.	2.67	15.83	0.00
.50	2.01	94.	2229.	5.33	15.83	0.00
1.00	3.20	94.	4642.	6.50	15.75	0.00


\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 29 AUG 78  
 \*\*\*\*\*

COI.  
 E>














PHOTO 1 Downstream View



PHOTO 2 Looking Upstream from  
Spillway



PHOTO 3 Looking Along Crest of Dam



PHOTO 4 Upstream From Face of Dam



PHOTO 5 Spillway



PHOTO 6 Looking Downstream From  
Spillway



PHOTO 7    Looking Towards Lake From  
             Spillway



PHOTO 8    Spillway at Road Crossing



PHOTO 9 Discharge Valve



PHOTO 10 Marshy Area Near  
Downstream Toe of Dam

